




The wing mounted on the fuselage. Roof height precludes having the ship on wheels in this particular facility.



Fuselage, looking toward the rear



This shows the matching of the new cabin interior material with an original door panel, shown top-center-right. We had to remove some old paint from the door panel to reveal the paint and texture of the original two-tone interior.



The cockpit is coming together.



Entry door.



Checking the engine mounts



This ship has one fold out writing desk and wicker chairs.



Tail section



1077 was taken outside in May for further rigging work



A better look at the center section and right engine mounted.